Commanding Officer USCG Loran Station Box 19 FPO, San Francisco 96652

3262 22 April 1971

From: Commanding Officer, Coast Guard Loran Station Talampulan, R. P.

To: Commander, Fourteenth Coast Guard District (o)
Via: Commander, Coast Guard Section, Philippines

Subj: Excessive unusable service time; report concerning

Ref: (a) CG-222, CCGD14 Supp. C-17

- 1. In accordance with CG-22 App C, CCGD14-C-17 letter report is hereby made discussing the sub-99.70 item 16 entry for rate 1L6 this month. It is noted that report-worthy difficulties evolved only with 1L6 while 1L7 performance was fine. Lorsta Naulo P. and Lorsta Talampulan commanding officers discussed the situation in mid-month to attempt to ease and correct the mounting bad time record on that rate.
- 2. Some few specifics may be pointed out to account for certain chunks of bad time. On 10 April the log here records 29.9 minutes of master off-air. On 16 April electronics personnel here experienced a full evening of difficult atmospherics aggravated by an instance of watchstander error here in failure to maintain a full 120 volts on the loran power line, the combination of which cost approximately 20 minutes. On 19 April an additional 22.2 minutes is recorded lost due to master off-air. Communication with the master indicated they had transmitter difficulty.
- 3. The general heavy accumulation of bad time during the report period was discussed and examined with electronics personnel both USCG assigned, and the Philippine Coast Guard loran trainees on board, who are currently standing all loran watches. Results of these discussions may be summarized as foldows:
- a. Communications problems and slowness, both between watchstanders on one station (as to passing on pertinent information to reliefs) and over the radio between stations has most probably been the largest single factor in impeding corrective action in each specific instance.
- b. With a preponderance of new watchstanders aboard, it is inevitable that there will be more instances of the watchstander taking extra time to assess an incident before realizing he must call an ET.
- c. New Watchstanders and station personnel have been found in general to be a bit slow in responding on-the-double to in-loran warning signals and the station ET horn.

Subj: Excessive unusable service time; report concerning

4. Extra instruction and extra watchstanders meetings have taken place to lay practical emphasis on increased teamwork response. Increased rigor is in evidence as witnessed by the improved record since the particularly bad period in mid-month. It is felt that communications familiarity and watchstanding experience will cause the required performance level to be met.

10550/3262 20 May 1971

FIRST ENDORSEMENT on CGLORSTA CATANDUANES Report of Loran Station Operation and Electronics Engineering for period 1 April 1971 to 23 April 1971 (CG-2899)

From: Commander, Coast Guard Section, Philippines
To: Commander, Fourteenth Coast Guard District (e)

- 1. All periods of unusual blink time are attributed directly to inexperienced personnel of the Philippine Coast Guard who were on watch when these occurrences happened. Although USCG senior technician was aboard each station, they were not notified according to the existing stations' instructions of bad time in progress. The Philippine Coast Guard were slow to respond to system malfunctions.
- 2. Since the station has been reverted to the Philippine Government, it is not possible to correct the USCG crew which was there. The USCG Section Office has brought the problem of poor watchstanding to the attention of HQ Philippine Coast Guard Stations with the action being taken of sending combined parties of USCG and PCG personnel to the loran stations in an effort to troubleshoot the suspected problems and work in a coordinated effort to continue the integrity of the loran system. This work is underway at this time and is expected to be a continuing requirement until 1974 when the U. S. Government reevaluates its agreement with the Government of the Philippines.

S. J. STEPHANY