

Commander
U.S. Coast Guard Section
APO, San Francisco 96528

4950
10 December 1971

From: Commander, Coast Guard Section, Philippines
To: Commander, Fourteenth Coast Guard District (e)

Subj: Philippine Loran Chain Engineering and Electronics Reports

1. COMPHILSEC has requested the Philippine Coast Guard to complete and forward to this office the following reports:

- a. CG-2899 Report of Loran Station Operation and Electronics Engineering.
- b. CG-4067 Report of Loran-A Systems Performance Test.
- c. CG-4334 Electronics Installation Change and Maintenance Report.
- d. Quarterly Tower Inspection Report.
- e. Completed Loran-A Recorder Charts.
- f. Time Difference Change Logs (Batan and Catanduanes only).
- g. COMPHILSEC Engineering Form 2 (copy enclosed).

2. These reports are not required by the Loran Turnover Agreement and are averaging two months in preparation and are sometimes as much as four months late.

3. To date only Form CG-4334 has been forwarded. All others are reviewed and corrected by COMPHILSEC, the original filed, and corrected copies returned to the unit.

4. Request advise if copies of any reports listed in paragraph 1 are required by CCGD14 or the Commandant.

R. E. HOOVER

Encl: (1) COMPHILSEC Engineering Form 2